TORQUE HINGES

DAMPER HINGES

ASSIST HINGES

HEAVY DUTY CONCEALED HINGE J95



Picture above is the combination of concealed hinge and mounting plate (sold separately)

RoHS	CAD	Item Code	Item Name	Туре	Material	Finish	Weight (g)	Box (pcs)
G	30	160-033-660	J95-24/0T	Without Catch		Nickel	148	50
G"	30	160-033-659	J95-C24/0T	With Catch	Body/Steel,	Nickei	160	50
G'	30	-	J95-24/0T BN	Without Catch	Cup/Zinc Alloy (ZDC)	Black	148	50
G'	30	-	J95-C24/0T BN	With Catch	Alloy (ZDC)	Nickel	160	50

A mounting plate (sold separately) is required for installation. Please order separately.

[Sold Separately]

- Mounting plate J95-P6T
 Face plate for glass door GH-J95FP
- Safety cover J95SC-0GR 3 Cover for mounting plate J95ZC-GR 4

[Recommended Screws]

M5 countersunk head screw. M5 raised countersunk head

DETENT HINGES

■In case of sheet metal door

BUTT HINGES

PIANO HINGES

STEP HINGES

LIFT-OFF HINGES

PIVOT HINGES

SPRING HINGES


CLEAN ROOM HINGES


HINGES FOR ALUMINIUM FRAME

DROP

GLASS DOOR HINGES

SPECIAL HINGES





Bore Distance (C)]				Ta	able-1
Bore Distance (C)	3	4	5	6	7	8
Door Gan (b)	6	5	1	3	2	1

Door gap can be adjusted by turning the overlay

[Opening Clearance (O.C.)]

Clearances for door edge O.C. (A) and hinge side O.C. (B) are necessary. O.C. (A) and (B) change depending on door thickness and bore distance (C).Refer to locus chart and tables below when designing cabinets.

O.C.(B)					7	Table-2	
Door Thickness	Bore Distance (C)						
(D)	3	4	5	6	7	8	
18	0	0	0	0	0	0	
20	0	0	0	0	0	0	
22	0.1	0.1	0.1	0.1	0	0.1	
24	0.1	0.1	0.1	0.1	0.1	0.1	
26	0.3	0.3	0.3	0.3	0.3	0.3	
28	1.7	1.1	0.6	0.5	0.5	0.5	
30	3.5	2.9	2.3	1.8	1.0	0.9	
32%	5.4	4.7	4.1	3.6	3.0	2.5	
34%	7.3	6.6	6.0	5.4	4.8	4.3	
	1		0.0	/R)			

*Please refer to the locus chart if door thickness is over 30 mm.(O.C. (B) can be made smaller by R chamfering (round chamfer) or C chamfering (chamfer plane) on the door)

Door Thickness			Do	or Wi	dth			
(D)	300	400	500	600	700	800	900	
30	0.9	0.6	0.5	0.4	0.4	0.3	0.3	

[Door Dimensions and Number of Hinges] 6

Refer to 1 4: P.108, 2: P.110, 3: P.109, 5: P.111, 6: P.100